

INSTALLATION INSTRUCTION
Low Voltage - Clamp Mount Spot Lights
DL-214

WAC LIGHTING
Responsible Lighting®

SAFETY INSTRUCTION

WARNING – To reduce the risk of FIRE, ELECTRIC SHOCK, EXPOSURE TO EXCESSIVE UV RADIATION, and OR INJURY TO PERSONS:

- Turn off/unplug and allow cooling before replacing bulb (lamp).
- Bulb (lamp) gets HOT quickly! Only contact switch/plug when turning on.
- Do not touch hot lens, or guard.
- Do not remain in light if skin feels warm.
- Do not look directly at lighted lamp.
- Keep lamp away from materials that may burn.
- Use only with a 50-watt or smaller bulb (lamp).
- Do not touch the bulb (lamp) at any time. Use a soft cloth. Oil from skin may damage bulb (lamp).
- Do not operate the luminaire with a missing guard.

SAVE THESE INSTRUCTIONS

INSTALLING LAMP:

1. Use a 12V MR16-G or MR11-G (UV protected & glass covered lamp), 50watt maximum (purchase separately).
2. Align lamp pins with socket holes and gently press in.

INSTALLING CLAMP:

1. Installs on a firm flat surface, such as wood, particleboard, cubicle partition etc. Standard clamp accommodates surfaces ½" to 2 1/2" wide.
2. Use the angle adjustment knob on the side to change the angle.
3. Flexible arm allows multiple aiming angles

ACCESSORIES:

1. Supplied with standard clamp that opens to 2 ½' wide.
2. An optional "DLC-4" clamp opens to 4".
3. An optional DLC-P clamp works on 2 1/2" pipe
4. Various accessory lenses and lamp shields are available.