

INSTALLATION INSTRUCTION

Focus - Low Voltage Quick Connect™ Fixtures

QF-199

WAC LIGHTING

Responsible Lighting®

INSTRUCTIONS PERTAINING TO A RISK OF FIRE, OR INJURY

IMPORTANT: NEVER attempt any work without shutting off the electricity.

- Lighted lamp is HOT!
- WARNING- To reduce the risk of FIRE OR INJURY:
- Turn off all power and allow to cool before replacing lamp.
- Lamp gets HOT quickly! Contact only switch/plug when turning on.
- Do not touch lens, guard, or enclosure.
- Keep away from materials that may burn.
- Do not touch the lamp at any time. Use a soft cloth.
Oil from skin may damage lamp.
- Do not operate the luminaire with a missing lens or damaged shield.
- Save these instructions.

OVERVIEW

Fixtures are designed for use with all WAC quick connect adapters.

They may also be used on other manufacturers brand of quick connect (consult factory for compatibility).

This fixture may be mounted to Solorail, Monopoints, or standard track, by coupling to a female quick connect adapter. Fixture can only be used on 12 volt systems.


INSTALLING LAMP & SHADE:

1. Compress the Lens retaining spring and remove. The concave lens will then drop out.
2. Connect the wire leads from the socket to each of the screw terminals on the back of the lamp.
3. Use an AR111 lamp, 12V 50 watt maximum .
4. Replace the concave lens and retaining spring. Make sure the retaining ring is completely seated in the groove of the fixture.

INSTALLING THE QUICK CONNECT:

1. Insert the post of the quick connect into the quick connect adapter.
2. Thread the top half of the conical section until it seats with the adapter.
3. Adjust fixture position, use caution not to loosen the conical section.

Retain instructions for future reference.



Installing to quick connect adapter



Example: Solorail Quick Connect Adapter



Top Conical Section

WAC Lighting

www.waclighting.com

Phone (800) 526.2588 • Fax (800) 526.2585

Headquarters/Eastern Distribution Center

44 Harbor Park Drive • Port Washington, NY 11050

Phone (516) 515.5000 • Fax (516) 515.5050

Western Distribution Center

1750 Archibald Ave • Ontario, CA 91761

Phone (800) 526.2588 • Fax (800) 526.2585